RECEIVED

MAR 0 2 1993 32/1/20h

DEPT. OF ECOLOGY

WATER WELL REPORT STATE OF MASHINGTON Start Card No. 048264 Water Right Permit No.

STATE OF W	ASHINGTON Water Right Permit No.
(1) OWNER: Name ROLLING HILLS/LEE JOHNSON Address 2343 (I VAN DAN ROAD COUPEVILLE, WA 98239-
(2) LOCATION OF WELL: County ISLAND - SE 1/4 NE 1/4 Sec 20 T 32 N., R 1 MM (2a) STREET ADDRESS OF WELL (or nearest address) 1126 N SIDNEY, DAK HBR	
(3) PROPOSED USE: MUNICIPAL	(10) WELL LOG
(4) TYPE OF WORK: Owner's Number of well (If more than one) NEW WELL Method: ROTARY	Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change in formation.
(5) DIMENSIONS: Diameter of well 8 inches Drilled 271 ft. Depth of completed well 271 ft.	HATERIAL FROM 1 TO
(6) CONSTRUCTION DETAILS: Casing installed: 8 " Dia. from 0 ft. to 261 ft. MELDED " Dia. from ft. to ft. " Dia. from ft. to ft.	BROWN CLAY & GRAVEL 33 57 13 58 57 113 58 59 57 113 58 59 59 59 59 59 59 59
Perforations: NO Type of perforator used SIZE of perforations in. by in. perforations from ft. to ft. perforations from ft. to ft. perforations from ft. to ft.	COARSE SAND MATER MOOD 164 189 189 230 189 230 242 273 273
Screens: YES Manufacturer's Name Type STAINLESS STEEL Hodel No. Diam. 8 slot size 40 from 261 ft. to 271 ft. Diam. slot size from ft. to ft.	2 ft stick up
Gravel packed: ND Size of gravel Gravel placed from ft. to ft.	Well Located According to
Surface seal: YES To what depth? 18 ft. Material used in seal BENTONITE Did any strata contain unusable water? NO Type of water? Depth of strata ft. Method of sealing strata off	·
(7) PUMP: Manufacturer's Name Type H.P.	
(8) WATER LEVELS: Land-surface elevation above mean sea level ft. Static level 118 ft. below top of well Date 01/27/93 Artesian Pressure lbs. per square inch Date Artesian water controlled by	Work started 01/25/93 Completed 01/27/93
(9) WELL TESTS: Drawdown is amount water level is lowered below static level. Was a pump test made? If yes, by whom? Yield: gal./min with ft. drawdown after hrs.	WELL CONSTRUCTOR CERTIFICATION: I constructed and/or accept responsibility for con- struction of this well, and its compliance with all
Recovery data Time Water Level Time Water Level Time Water Level	1
Date of test / / Bailer test	ADDRESS PO BOX 422, BURLINGTON, WA [SIGNED] License No. 0623 Contractor's Registration No. DAHLMPW123LC Date 01/29/93